Monday, 22/10/2007 2:17:19 PM Linda Lacelle **Process Sheet** Customer : CU-DARQQ1 Dart Helicopters Services **Drawing Name** : ARM Job Number **Estimate Number** : 12883 P.O. Number Part Number : D3560043 : D3560 UNDER REVIEW : 22/10/2007 S.O. No. : This Issue **Drawing Number** Prsht Rev. : NC : N/A Project Number : 11 First Issue Type : SMALL /MED FAB : C **Drawing Revision** : 35031 Previous Run Material Each **Due Date** : 29/10/2007 Written By Checked & Approved By Comment : Est Rev:A New Issue 07.05.24 EC Est Rev B ECN 987 07.10.09 EC Additional Product Job Number: Machine Or Operation: Seq. #: Description: 1.0 M6061T6B0500X05000 6061-T6 Bar .50" x 5.0" Comment: Qtv.: 1.3598 f(s)/Unit Total: 19.0365 f(s) 6061-T6 Bar 0.50" x 5.00" Batch: M/06/182 BAND SAW 2.0 BAND SAW Comment: BAND SAW Cut blanks 15.500" long HAAS1 3.0 HAAS CNC VERTICAL MACHINING #1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA695 Rev: A Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC8 SECOND CHECK Comment: SECOND CHECK

Dai: 1710	oopaoi									
W/O:			WC	ORK ORDER CHANGE	ES					19
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	D	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ē					1		
			11							
Part No		PAR #:	Fault Cate	gory:						
					Q/	A: N/C	Closed	:	_ Date: _	
NCR:			The same	ER NON-CONFORMA	NCE (N	CR)				1 1
DATE	STEP	Description of NC	Initial	Corrective Action Section		ın &	Verific		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		ate	Section	n C	Chief Eng	QC Inspector
									- 6	
										100

Monday, 22/10/2007 2:17:19 PM Date: User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35297 Part Number: D3560043 Job Number: Seq. #: Machine Or Operation: Description: 6.0 D35921 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) PLATE LARGE FAB 1 7.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (8- on one side weld from bottom to top half way 9- same for other side (half way) SP 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) QC5 INSPECT WORK TO CURRENT STEP 8.0 Comment: INSPECT WORK TO CURRENT STEP 9.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 11.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

Dart Ae	rospace	e Ltd							
W/O:			W	ORK ORDER CHANGES					
DATE	STEP	PR	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng./ Prod Mgr	Approval QC Inspector
						6			(e)
Part No		PAR #:	Fault Cate	egory: NC	R: Yes N	lo DQA		Date:	3.99
4								_ Date: _	
NCR:			WORK ORD	ER NON-CONFORMANCE	E (NCR)				- 4
		Description of NC		Corrective Action Section B		Verifica	tion	Ammanual	Ammanathi
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Approval Chief Eng	Approval QC Inspector
a million									_
	Flan 5								
	No.	200 PER 101 TO 1							- 31

Date: Monday, 22/10/2007 2:17:19 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35297 Part Number: D3560043 Job Number: Seq. #: Machine Or Operation: Description: 12.0 D2808 Spacer Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) Spacer batch: 13.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 QC5 INSPECT WORK TO CURRENT Comment: INSPEC CURRENT STEP 15.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 16.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion


		The state of the s								
W/O:			V	ORK ORDER CHANG	ES					
DATE	STEP	PROG	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Ŧ										
										0.0
Part No		PAR #:	_ Fault Ca	tegory:	NCF	R: Yes	No DQA	\:	_ Date: _	
3									_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE	(NCR)			19
		Description of NC		Corrective Action Section	on B		Verific	ation	Approval	Anneous
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Approval Chief Eng	Approval QC Inspector
										71
	11 11									
N N										
	300	Course Course 1 1 to 1 a								


D3560-1 ARM (-041, SHOWN) OR D3560-2 ARM (-042, OPPOSITE) D3592-1 PLATE, SEE DETAIL A

> D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)

D3560-3 ARM (-043, SHOWN) OR 03550-4 ARM (-044, OPPOSITE) D3592-1 PLATE, -SEE DETAIL A

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)





DETAIL A (SCALE 1:1)

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES




UNDER REVIEW


07.10.22 DE

	C		07.06.19	REMOVE POWE	DER COAT
	В		07.01.15	REDESIGN AS	WELDMENT, ADD POCKETS
	A		06.09.25	NEW ISSUE	
COPYNIGHT @ 2008 BY DART AEROSPACE LTD.	DESIGN	9	DRAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKE	°H	APPROVED #	D3560	REV. (
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM	DATE			TITLE	SCALI
DART AEROSPACE LTD.	07.06	5.19		ARM WELDMEN	T to

E WILLIAM										
W/O:			V	VORK ORDER CHANG	ES					3
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Da	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										T AV
										-3
										A S
Part No		PAR #:	Fault Ca	tegory:	NCR: Y	es No	DQA:		_ Date: _	
		は特性			QA	: N/C (Closed:		_ Date: _	
NCR:			VORK OR	DER NON-CONFORMA	NCE (N	CR)				
DATE		Description of NC		Corrective Action Section		,	/erifica	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section		Chief Eng	QC Inspector
										1
										1
										4
										125
	€ 11 -									
										1.4



1 1 1 1 1 1 1 1 1								
W/O:			٧	VORK ORDER CHANGE	S			
DATE	STEP	PR	OCEDURE CI	HANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1
Part No		PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA:	Date: _	
as/10					QA: N/	C Closed:	Date: _	
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCR)		
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
								3



W/O:	Sid.		V	VORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Car	tegory:	NCR	: Yes	No DQA	\:	_ Date: _	
						QA: N	/C Closed	:	_ Date: _	
NCR:		V	VORK OR	DER NON-CONFORMA	NCE	(NCR)			b
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DAIL	3,12	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
b			<u>.</u>							-
							74	-		

DART AEROSPACE LTD	Work Order:	35191
Description: Arm	Part Number:	D3560-3
Inspection Dwg: D3560 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	Prototype
---	---------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	5065				
Ø0.196	+0.005/-0.001	.196	/			
Ø1.000	+0.010/-0.001	1.000	_			
Ø0.90 <mark>0</mark>	+0.010/-0.001	.899	/			
0.500	+/-0.010	.502	/		-	
0.250	+/-0.010	.250	/			
0.275	+/-0.010	.276	/	22		
0.188	+/-0.010	.189	/			
2.000	+/-0.010	2.002	1			
1.750	+/-0.010	1.752	/			
1.702	+/-0.010	1.704	/			
Ø0.385 x 100°	+/-0.010 x 0.5°	.391	/			
0.250 Deep	+/-0.010	,250	1			101
1.0		10				
						34.5
	100					
						7

					_
Measured by:	Audited by:	J.L.	Prototype Approval:	N/A	
Date: 07/12/07	Date:	07/12/07	Date:	N/A	

Rev	Date	Change	Revised by	Approved
Α	07.01.17	New Issue	KJ/JLM	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM	

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								**	*
Part No:		PAR#:	Fault Category: NO			CR: Yes No DQA: Date:			
NCR:			WORK OR	DER NON-CONFORMAN				3	
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification		Approval	Approval
	SIEP		Initial Chief Eng	Action Description Chief Eng	Sign of Date	Section		Chief Eng	QC Inspector
							1	31	
								er.	
							担急		